

List of products scheduled for discontinuation

Ver.25.1

Parts No.	Products	Recommended replacement model (current)
B40827502XXX	SR3000 2SR40700:WR-B6016	URB7030. Specifications are partially different so please inquire
B40827503XXX	SR3000 2SR20450:UM-B6003	URB7030. Specifications are partially different so please inquire
B40832410AXX	DDS-LPS:WR-C2002-1	DDS-LPS3 (B40180001XXR) + Exchange kit
B40832413XXX	DDS-LPS II :W/R-C0007	DDS-LPS3 (B40180001XXR) + Exchange kit
B40833001XXX	C.UNIT-2.056:WR-C0020	Please inquire
B40833002XXX	C.UNIT-2.112:WR-C0021	Please inquire
B40833003XXX	C.UNIT-2.168:WR-C0022	Please inquire
B40833004XXX	C.UNIT-2.224:WR-C0023	Please inquire
B40833005XXX	C.UNIT-2.280:WR-C0024	Please inquire
B40833021XXX	C.UNIT-2.040:WR-C0030	Please inquire
B40833022XXX	C.UNIT-2.080:WR-C0031	Please inquire
B40833023XXX	C.UNIT-2.120:WR-C0032	Please inquire
B40833024XXX	C.UNIT-2.160:WR-C0033	Please inquire
B40833025XXX	C.UNIT-2.220:WR-C0034	Please inquire
B40833041XXX	C.UNIT-4.014:WR-C0025	Please inquire
B40833042XXX	C.UNIT-4.028:WR-C0026	Please inquire
B40833043XXX	C.UNIT-4.042:WR-C0027	Please inquire
B40833044XXX	C.UNIT-4.056:WR-C0028	Please inquire
B40833045XXX	C.UNIT-4.070:WR-C0029	Please inquire
B40833061XXX	C.UNIT-4.010:WR-C0035	Please inquire
B40833062XXX	C.UNIT-4.020:WR-C0036	Please inquire
B40833063XXX	C.UNIT-4.030:WR-C0037	Please inquire
B40833064XXX	C.UNIT-4.040:WR-C0038	Please inquire
B40833065XXX	C.UNIT-4.050:WR-C0039	Please inquire
B40842711XXX	SAEI-1:S-D4009	SAEI-2 (Need to change the encoder, PG cable and software.)
B40847603XXX	DCI-001(RoHS):S-Z1005-1	-
B40847604XXX	MFI-001(RoHS):S-Z1010-1	-