

List of discontinued products (available for repair and maintenance)

Ver.25.1

Parts No.	Products	Recommended replacement model (current)
B40108315XXX	Encoder:4096P:RP-5354D-CO-4096P/R	TS5016N60(B40108403XXX)
B40108316XXX	Encoder:RP-5354D-CO-10000P/R	TS5420N60(B40108412XXX)
B40108414XXX	Absolute Encoder Tamagawa:TS5778N155	B40108414AXX(without ABS Cable: MSW1-4096-13N11-12WR/MTL) or B40108415AXX(with ABS Cable: WS300:MSW1-4096-13N11-12WS/MTL). Specifications are partially different so please inquire.
B40108415XXX	Absolute Encoder Tamagawa:TS5778N157	B40108414AXX(without ABS Cable: MSW1-4096-13N11-12WR/MTL) or B40108415AXX(with ABS Cable: WS300:MSW1-4096-13N11-12WS/MTL). Specifications are partially different so please inquire.
B40173401XXX		ICA-1 (CC-LINK): Specifications are partially different so please inquire
B40811403XXX		FR1000: Specifications are partially different so please inquire
B40811404XXX		FR1000: Specifications are partially different so please inquire
B40811405XXX	S1000 S2FC-1100:W/R-21126-2	FR1100: Specifications are partially different so please inquire
B40811602XXX	S1000 CCC:S-25018	-
B40824735AXX	BRU 200 PAMJ-2 R0.4:S-B4018	PAMJ-3A(B40824793XXX), Specifications are partially different so please inquire.
B40826311XXX	SS4000 SS4437:UM-B0001	SS4437A(B40826311AXR), B40826311XXX cannot be used together in a parallel configuration.
B40826312XXX	SS4000 SS4437P:UM-B0007	SS4437AP(B40826312AXR), B40826312XXX cannot be used together in a parallel configuration.
B40826373XXX	SS4000; SS4275(W); UM-B0066;	SS4265A(B40826373BXR), B40826373XXX cannot be used together in a parallel configuration.
B40826374XXX	SS4000; SS4275P(W); UM-B0067;	SS4265AP(B40826374BXR), B40826374XXX cannot be used together in a parallel configuration.
B40827007AXX	GV3000 15HP/230V:15V2160	UDM2058A(B40850008AXR) or UDM2058A(B40850008ASR). Specifications are partially different so please inquire. No NEMA type.
B40827008AXX	GV3000 20HP/230V:WR-B6008,20V2160	UDM2071A(B40850005AXR) or UDM2071A(B40850005ASR). Specifications are partially different so please inquire. No NEMA type.
B40827011AXX	GV3000 40HP/230V:UM-B6001,40V2060	UDM2141A(B40850006AXR) or UDM2141A(B40850006ASR). Specifications are partially different so please inquire. No NEMA type.
B40827142XXX	GV3000 50V4060:UM-B6014	UDM4071A(B40850105AXR) or UDM4071A(B40850105ASR). Specifications are partially different so please inquire. No NEMA type.
B40827143XXX	GV3000 60V4060:UM-B6015	UDM4141A(B40850106AXR) or UDM4141A(B40850106ASR). Specifications are partially different so please inquire. No NEMA type.
B40827151XXX	GV3000 1V4160:UM-B6016	UDM4004A(B40850101AXR) or UDM4004A(B40850101ASR). Specifications are partially different so please inquire. No NEMA type.
B40827152XXX	GV3000 2V4160:UM-B6018	UDM4004A(B40850101AXR) or UDM4004A(B40850101ASR). Specifications are partially different so please inquire. No NEMA type.
B40827223AXX	GV3 3HP/230V N.X4/12	UDM2022A(B40850002AXR) or UDM2022A(B40850002ASR). Specifications are partially different so please inquire. No NEMA type.
B40827501XXX	SR3000 2SR20300:WR-B6012	URB7030: Specifications are partially different so please inquire
B40827917XXX	GV3 NEMA1 KIT 75/100	-
B40828051XXX	PF700Se 220K/460V L:UM-B8007	-
B40829501XXX		VZ7000 Terminal
B40832405XXX	DDS CR:W/R-63075	-
B40832408XXX	DDS PI2:MC-C2001	-
B40842501XXX	PSC PCT-1B:MB-D5006-A	-
B40842502XXX	PSC PCT-1D:MB-D5014	-
B40842503XXX	PSC PCT-2B:MB-D5016	-
B40842720XXX	PIOI-1:S-D4025	PSC7000(B40843301XXX)
B40842721XXX	SRO-1:S-D4026	-
B40842722XXX	PDIO-1:S-D4027	PSC7000(B40843301XXX)
B40842724XXX	SRS-1:S-D5083	-
B40843705XXX	PSC7000 DSPM-1A :S-D4031	DSPM-2A(B40843610XXX). Specifications are partially different so please inquire.
B40884013XXX	DCS 5~24V OUT CABLE3:M-81450	-

List of discontinued products (available for repair and maintenance) Ver.25.1

Parts No.	Products	Recommended replacement model (current)
B4R108414XXX	TS5778N155	MSW1-4096-13N11-12 Series+SAEI-2: Specifications are partially different so please inquire
B4R108415XXX	TS5778N157	MSW1-4096-13N11-12 Series+SAEI-2: Specifications are partially different so please inquire